

The assembly process is shown in eight steps:

- Step 1: A metal bracket is shown being attached to a wall using a screw. An orange arrow indicates the direction of the screw.
- Step 2: A cable is inserted into the bracket. An orange arrow indicates the direction of the cable.
- Step 3: The cable is secured by a small metal pin. An orange arrow indicates the direction of the pin.
- Step 4: The final assembly is shown. An orange arrow indicates the direction of the cable. The text  $\pm 2,5 \text{ mm}$  is shown, indicating the tolerance for the cable's position.